

A. 1071

25X1A

B. 15/1924Z

C. MISSION UNSUCCESSFUL. NR ONE FILTER DID NOT CHANGE AT INITIAL SELECTION. CONTINUED ATTEMPTS GOT NR TWO FILTER IN PLACE AFTER 50 MIN. UNABLE EXPOSE NR 3 FILTER. ACFT OUT. RIGHT SLIPPER RETAINED 40-50 GAL FUEL.

END OF MESSAGE

Copy No.

25X1A